

# SDI switch command strings

## Setting Parameters :

Baud rate: 9600

Data bits: 8

Stop bits: 1

Parity bits: No

## Commands :

**1. Data format :** Hex code

**2. Format :**

Switch to input 1: 0xAA 0xCC 0x01 0x01

Switch to input 2: 0xAA 0xCC 0x01 0x02

Switch to input 3: 0xAA 0xCC 0x01 0x03

Switch to input 4: 0xAA 0xCC 0x01 0x04